

Annexure D

BUILDING SAFETY CERTIFICATE

No. 140/4सी

Dated: 28/06/2024

It is certified that the existing building Ek Omkar Global Academy (name of the building or premises) at IGL Road, Barakhari, Kashipur (U.S. Nagar) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	02 (G.F+1st)	01 (G.F.)	N.A.	N.A.	N.A.	N.A.

The building is owned/occupied by Ek Omkar Global Academy (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. Kashipur (Name of Department/ Govt.) on 28/06/2024 (date of inspection) in the presence of Shri Fateh Singh (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 28/06/2024 for a period of 10 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Proper maintenance the Building is necessary condition.
- 2.
- 3.
- 4.

Issued on 28/6/2024 at Kashipur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: Praveer Alam 28/6/2024

Name: PRAVEER ALAM

Designation: Assistant Engineer

Name & Address of Department/ Office: _____

Construction Division, PWD Kashipur (US Nagar)

E- Mail ID : sepwdksp@gmail.com

Phone No
Fax No

05947-275230
05947-278797

Dated- 31/08/2022

Letter No. 131 / 4 अ.

To,

The Principal
Ek Onkar Global Academy
IGL Road, Lohiyapul / Barkheri,
Kashipur Distt- U.S. Nagar

Subject:- Safety certificate of school building regarding.

Refrence:- Your office letter No. EOGA /2022-23/06 Dated
29-08-2022.

Dear Sir/Madam,

With reference to above, Ek Onkar Global Academy, IGL Road, Lohiyapul / Barkheri, Kashipur is inspected on dated 31-08-2022. The built up structure of Ek Onkar Global Academy in R.C.C. framed structure. The school building is structurally safe and in good habitable condition. The school building is safe for academic activities as on date 31-08-2022.

P. Lom

31/8/2022

सहायक अभियंता,
वि.सं.ग. शा.सं. लो. ग्लो. अका.
कशीपुर (उ.स. नगर)